


GRBL 4 Axis Controller



Please note the positive and negative poles, make the right connection.

Grbl Wiki


https://github.com/gnea/grbl/wiki


Recommended Control Software https://github.com/Denvi/Candle


CH340 Driver

http://www.wch-ic.com/search?t=all&q=USB+to+serial+port

Current adjustment method: multimeter measures the voltage between potentiometer center and GND, A4988 only needs to plug in USB, DRV8825 and TMC2208 need to plug in 24V, Non professionals, please do not adjust at will.








The current setting reference voltage measurement diagram is shown as above $I_{Tripmax} = V_{ref}/(8*Rcs) \ Rcs = 0.1\Omega$

Factory default current: 2.5A Maximum drive current: 2.5A



The current setting reference voltage measurement diagram is shown as above ITripmax = Vref*2.0

Factory default current: 1.0A Maximum drive current: 1.4A



The current setting reference voltage measurement diagram is shown as above Itripmax = Vref/1.4

A4988



DRV8825

ENABLE	*	2000		VIMOT
MS1	6		逦	GND
MS2	6		1	2B
MS3	*	¹ 4	÷	1B
RESET	*	652611651125111	(4)	1A
SLEEP	6	CERANG ()	(F)	2A
STEP	0	111111111111111111111111111111111111111	9	VDD
DIR	6	told hore was		GND

TMC2208

11102200				
EN	⊕BN (⊕) • VM (⊕)	VM		
MS1	⊕MS1 GND ⊕	GND		
MS2	→MS2 M1B →	M1B		
PND	⊕PDN :8.36 M1A €	M1A		
USART	JUSART MZA 6	M2A		
CLK	⊕CLK M2B €	M2B		
STEP	STEP VIO	VIO		
DIR	ODIR GND	GND		

Microstep	M21	MSZ	M23
Full Step	Low	Low	Low
1/2 Step	High	Low	Low
1/4 Step	Low	High	Low
1/8 Step	High	High	Low
1/16 Step	High	High	High

Microstep	MS1	MS2	MS3
Full Step	Low	Low	Low
1/2 Step	High	Low	Low
1/4 Step	Low	High	Low
1/8 Step	Hìgh	High	Low
1/16 Step	Low	Low	High
1/32 Step	High	Low	High
1/32 Step	Low	High	High
1/32 Step	High	High	High

Microstep	MS1	MS2
1/2 Step	High	Low
1/4 Step	Low	High
1/8 Step	Low	Low
	High	High

